

Internal Monitoring (Inspection/Verification) of CAMPA works executed in 2019-20

Name of the Forest Division: Soil and Water Conservation Division Kupwara

Component (Please Tick)			Name of the Unit- Forest Comptt./ Range	Coordinate (Lat/Long)	Area treated (In Ha.)	Fencing (RFT)	Planting (Spp. Wise number of plants planted)	Soil & Water Conservation Works)			Inspection (the highest level to have inspected)/ remarks if any	Remarks
CA	NVP	RSP						DRSM	Crate (No.)	WHS (No.)		
CA	Nil	Nil	Co,32 Budwan Karnah	34,23,15.56-N 73,53,48.23 -E	-	-	-	-	-	-	50%	Being a hilly and farflung area which remained covered with snow till ending March, the pit work for both fencing and planting was taken up simultanously and upto around more than 50% pit work for both planting and fencing was done & work was under full pace, when COVID-19 restrictions were fully imposed and work was stoped. However material component to the amount of Rs.4.05111 Lacs has been booked and the material items including barbed wire angle iron fence posts and sign board/gate has been dumped at the working site Co. 32 Budwan karnah under the custody of concerned Zonal Officer.
Sub-total					0	0	0	0	0	0	0	

Name of the Forest Division (Soil & Water conservation Division Baramulla)

	NPV		Zaloor 23K Kandi Range Kamraj Division	Lt. 34o-25'-04.5" N Lo. 74o-22'-08.6" E	17	3000	6000 Ulmus= 3500 Robinia= 2500	90	12	0	DSCO (inspected & verified works 50% .The works executed were Found Satisfactory /up to the mark both Qualitatively & Quantitatively)	
Sub-total					17	3000	12000	90	12	0		

Name of the Forest Division : Soil & Water Consevation Division Anantnag/Kulgam

District Anantnag												
			Harkhan Daksum Comptt.No. 18/K Daksum Range	N33 36 19.76 E0.75 27 17.14	6 Ha	1500	2243 of Robinea Spss.	60	2	Nil	Nil	
Sub-total					6	1500	2243	60	2	0		

Component (Please Tick)			Name of the Unit- Forest Comptt./ Range	Coordinate (Lat/Long)	Area treated (In Ha.)	Fencing (RFT)	Planting (Spp. Wise number of plants planted)	Soil & Water Conservation Works)			Inspection (the highest level to have inspected)/ remarks if any	Remarks
CA	NVP	RSP						DRSM	Crate (No.)	WHS (No.)		
District Kulgam												
			Gancure Waltengo Comptt.No. 38/N Qazigund Range	N 33 32 8.73 E 075 06 3.29	6 Ha	1500	2243 of Robinea Spss.	50	5	Nil	Nil	
Sub-Total					6	1500	2243	50	7	0		
	Total				12	3000	4486	110	9	0		
Name of the Forest Division: _Samba												
Y			Sarna Patyari 55/D Samba	N 32-38'-050" E 075-07'-950"	22 ha	6000	10850 Anaar, Amroodh, Jamun, Bayda, Bamboo, Sarin.	150	5	4000	Internal verification has been conducted by the Deptt.and report stand submitted	
Sub-total					22	6000	10850	150	5	4000		
District Jammu 2019-20												
Y			Jambou Zoo	N 32-47'-14.73" E 74 52' 49.06"	--	--	5000	--	--	--	--	
Sub-total							5000					
District Soil Conservation Officer, Soil & Water Conservation Deptt. District Udhampur												
√	0	0	Jalamara (Tikri Udhampur), Co- 17/U	N- 32 56' 38.92" E- 075 00' 01.71"	10 Ha	3000	5000 Nos (P.Bagged) a) Gewelia Robusta - 800 Nos. b) Bamboo -1500 Nos c) Dalbergia Sissoo- 2000 Nos d) Mixed species- (Jammun, Arjun, Sapindus, Gauva, neem, Albizzia) -700 nos	40	0	0	Inspected by Joint Director, Soil & Water Conservation Deptt. Jammu & DSCO Udhampur	

Component (Please Tick)			Name of the Unit- Forest Comptt./ Range	Coordinate (Lat/Long)	Area treated (In Ha.)	Fencing (RFT)	Planting (Spp. Wise number of plants planted)	Soil & Water Conservation Works)			Inspection (the highest level to have inspected)/ remarks if any	Remarks
CA	NVP	RSP						DRSM	Crate (No.)	WHS (No.)		
√	0	0	Bapp, Co- 109/D (Mantalai)	N- 33 59' 24.37" E- 075 21' 26.90"	08 Ha	3000	5000 Nos (Naked Root) a) Robinia - 2000 Nos. b) Alamus - 1000 Nos c) Dalbergia Sissoo-400 Nos d) Amlok - 1000 Nos e) Chir - 600 Nos (P.B)	70	0	0	Inspected byDSCO Udhampur	
Sub-total					18	6000	1000	110	0	0		
District Soil Conservation Officer, Soil & Water Conservation Deptt. District Reasi												
√	0	0	Gangote Dogian Co-4/GG	N-33 18' 20.79" E- 74 50' 27.31"	20 Ha (fenced during the year 2017-18)	0	8000 Nos (Naked Root) plants planted in already fenced area during the year 2017-18 a) Dalbergia Sissoo- 2000 Nos b) Alamus - 2000 Nos c) Robina - 4000 nos	100	0	0	Inspected by DSCO Udhampur/Reasi	
total					20	0	8000	100	0	0		
Soil & Water Conservation Department Kathua												
			Saganu F.R.Jasrota	N32 ⁰ 12'58.00" E 75 ⁰ 11'57.46"	30	6000	15000 P.B. 7000 Sisal 8000	200	10	0	Joint Director Soil & Water Conservation Jammu Region Jammu	

Component (Please Tick)			Name of the Unit- Forest Comptt./ Range	Coordinate (Lat/Long)	Area treated (In Ha.)	Fencing (RFT)	Planting (Spp. Wise number of plants planted)	Soil & Water Conservation Works)			Inspection (the highest level to have inspected)/ remarks if any	Remarks
CA	NVP	RSP						DRSM	Crate (No.)	WHS (No.)		
			Ghard Maitr II 43-B / Batote (Old Closure 2018-19)	33°13'18.55"N 75°13'54.01"E	-	-	Robinia - 1636 Nos.	-	-	-	No inspection by highest level / Nil	
							Total 1636 Nos. Naked Root		-	-		
Sub-total					15	3500	13336	854	42	0		
Name of the Forest Division Soil & Water Conservation Forest Poonch.												
CA	-	-	Zone Nangali CO;167/H (New Closure)	33°-46'31.22 "N 074°-09'30.28"E	15 Ha.	5000	Robinia - 4000 Almus - 2000 Patches- 5000	70			No inspection by highest level / Nil	
			Kandyara CO:167/H (Old Closure) (BUC)	33°-46'52.1 "N 074° 09'33.7"E	-	-	Robinia - 3000			No inspection by highest level / Nil		
Sub-total					15	5000	9000	70				
Name of the Forest Division Rajouri (Soil & Water Conservation Department Rajouri)												
	ü		Ghambir Keri Co. 86-87/R Rajouri Range	N33° 31 18.99 E74° 17 38.99	10	3000	1. Allmus 1500 2. Rubenia15 00 3.	90	0	0	DSCO (inspected and verified works 50% the works executed found satisfactory/upto the mark both in Qualitatively and Quantitatively)	
	ü		Bakher Co. 42/D Sunderbani Range	N33° 05.519 E74° 17 43.30	10	3000	1. Sissoo 1600 2. Amla 50 3. Galaca 100 4. Bamboo	90	0	0		
Sub-total					20	6000	7000	180	0	0		
Name of the Forest Division Assistant Conservator of Forests , Department of Soil & Water Conservation , District Srinagar/ Ganderbal												
			Pashwan Khimber	LT: 34° 12'.287" N Lo: 74° 52' 688" E	10	3000	Rubinia = 7500	53	3	-	Site inspected by DSCO Srinagar the closure has been established on a rugged terrain to check the soil erosion during heavy runoff with an added treatment of Nalla's	
			Khimber Chatterhama	LT: 34° 11'.55.78" N Lo: 74° 52' 41.84" E	-	-	-	-	-	1		
Total					10	3000	8000	53	3	1		

Component (Please Tick)			Name of the Unit- Forest Comptt./ Range	Coordinate (Lat/Long)	Area treated (In Ha.)	Fencing (RFT)	Planting (Spp. Wise number of plants planted)	Soil & Water Conservation Works)			Inspection (the highest level to have inspected)/ remarks if any	Remarks
CA	NVP	RSP						DRSM	Crate (No.)	WHS (No.)		
Name of the Forest Division Assistant Conservator of Forests , Department of Soil & Water Conservation , District Pulwam/Shopian												
			Toolihalan Sedow No. V/2b and V/1a	33°39'56.6"N 74°45'52.6"E	0	0	0					only materials have been purchased
					0	0	0					
			Sudyali Sangerwani No.Ri- 24a	33° 47' 53.04"N 74° 41' 58.08"E								
Sub-Total					0	0	0					